

# PARTS DEPARTMENT BULLETIN

**DATE:** 9 JUNE 2003 **BULLETIN NUMBER:** 2003-1  
**TO:** ALL MASTER DISTRIBUTORS AND WESTERBEKE DEALERS  
**SUBJECT:** SEA WATER PUMP DRIVE BELT PART NUMBER CHANGE

SEA WATER PUMP DRIVE BELT #031152 IS CHANGED TO #044045.

REASON FOR THE CHANGE IS TO INCREASE THE SERVICE LIFE OF THE BELT.

MODELS AFFECTED: 20.0/16.0BEDA  
25.0/20.0BED  
32.0/25.0BEDA

PLEASE MAKE NOTE OF THIS CHANGE IN THE FOLLOWING PARTS LISTS:

PUBLICATION #042000 EDITION ONE 20.0/16.0BEDA PAGE 123 REF 7-2

PUBLICATION #040000 EDITION ONE 25.0/20.0BED PAGE PAGE 121 REF 8-2

PUBLICATION #041512 EDITION THREE 32.0/25.0BEDA PAGE 125 REF 8-2

CHANGE THESE REFERENCES (REF) TO PN#044045.

