

# PARTS DEPARTMENT BULLETIN

**DATE:** 29 MARCH 2004 **BULLETIN NUMBER:** 2004-5  
**TO:** ALL MASTER DISTRIBUTORS AND WESTERBEKE/UNIVERSAL DEALERS  
**SUBJECT:** CONTENT CHANGE – SPARE PARTS KITS “A” AND “B”

ALL SPARE PARTS KITS “A” AND “B” THAT PREVIOUSLY CONTAINED IMPELLER KITS #033100 OR #034440 AND SEA WATER PUMP REPAIR KITS #030718 OR #034466 FOR SEA WATER PUMP #033636 WILL BE REPLACED EFFECTIVE 1 MAY 2004 WITH KITS FOR THE NEW SEA WATER PUMP #048080.  
REFERENCE PARTS BULLETIN #2004-1 DATED 9 MARCH 2004.

IMPELLER KIT #033100 FOUND IN “A” & “B” KITS WILL BE REPLACED WITH IMPELLER KIT #048500 AND SEA WATER PUMP REPAIR KIT #030718 FOUND IN “B” KITS WILL BE REPLACED WITH SEA WATER PUMP REPAIR KIT #049000.

IMPELLER KIT #034440 FOUND IN “A” & “B” KITS WILL BE REPLACED WITH IMPELLER KIT #048500 AND SEA WATER PUMP REPAIR KIT #034466 FOUND IN “B” KITS WILL BE REPLACED WITH SEA WATER PUMP REPAIR KIT #049000.

CUSTOMERS PURCHASING “A” OR “B” KITS FOR THEIR ENGINES THAT HAVE THE #033636 PUMP WILL HAVE TO PURCHASE THE IMPELLER KIT OR REPAIR KIT SEPARATELY.

WESTERBEKE DISTRIBUTORS – PLEASE ENSURE THAT A COPY OF THIS BULLETIN IS SUPPLIED TO YOUR PARTS DEPARTMENT AND ALSO PLEASE PASS A COPY ON TO ALL OF YOUR SERVICING DEALERS.

