

SERVICE BULLETIN

DATE: 18 March 1983 BULLETIN NUMBER:
MODEL: All Marine Propulsion Engines 121
SUBJECT: Shift Cover Sealing

Shift covers on all HBW-Transmissions are now being mounted on the transmission by the manufacturer with loctite (orange) thus eliminating the use of the shift cover gasket (PN #22207).

This sealant will prevent the shift cover from moving out of its factory adjusted position even after removal of the 4 mounting bolts (PN#22208) and thus allow for the original factory adjusted shift pattern to be maintained.

IMPORTANT!

Removal or disturbing of the shift cover will void all warranty responsibility by Westerbeke.

Any HBW-Transmission suspect to defect during the warranty period specified by Westerbeke must be returned with the shift cover undisturbed and in its original position. Prior approval must be obtained for all HBW-Transmissions to be removed, repaired, or returned (R.G.A.) under warranty.

To: Master Distributors