



# PARTS DEPARTMENT BULLETIN

DATE: 3-Apr-18

BULLETIN NUMBER: 2018-1

SUBJECT: Exhaust mixing elbow changed to reduce potential backpressure.

## MODELS

AFFECTED: 16.0 BEDA 50HZ, 16.0 BED 50HZ, 20.0 BED 60HZ, 20.0 BEDA 60HZ, 20.0 BED 50HZ, 25.0 BED 60HZ, 71C Four, 82B Four

DETAIL: Products manufactured after January 2000 (serial number date code E001) were manufactured with 3" outlet exhaust mixing elbows in an effort to reduce potential exhaust backpressure in some applications.

When ordering replacement exhaust mixing elbows for affected products it is best to check the outlet size in advance. Generator products with 2" exhaust hose / elbow outlets use Exhaust Mixing Elbow Kit PN 38760 and those with 3" exhaust hose / elbow outlets use Exhaust Mixing Elbow Kit 39334. Propulsion engines with 3" outlet diameters use Elbow Kit PN 39334 for 70 degree, and Elbow Kit PN 49762 for 45 degree mixing elbow applications.

WESTERBEKE CORPORATION

Myles Standish Industrial Park, 150 John Hancock Road, Taunton, MA 02780-7319 • Tel: 508.823.7677 • Fax: 508.884.9688

[www.westerbeke.com](http://www.westerbeke.com)