

SERVICE BULLETIN

DATE: May 1, 1980

BULLETIN NUMBER: 107

MODEL: All Models

SUBJECT: Thermostats

Beginning approximately May, 1980, thermostats supplied by the factory have a by-pass hole sufficient to allow adequate water flow through the exhaust manifold, head, and block, during engine warm-up.

This flow is mandatory, especially in the case of marine engines and generator sets which have significant load applied soon after start-up.

We strongly recommend that only genuine WESTERBEKE thermostats be used in WESTERBEKE products to assure proper design in this regard.



J. H. WESTERBEKE CORP.

AVON INDUSTRIAL PARK, AVON, MASS. 02222 (617) 588-7700
CABLE: WESTCORP, AVON-TELEX: 92-4444